

examunion

Certified IT Exam Material Authority



Accurate study guides, High passing rate!
We offer free update service for one year!
<http://www.examunion.com>

Exam : SVC-16A

**Title : Apple Service
Fundamentals**

Version : Demo

1.What color indicates that the Liquid Contact Indicators inside a MacBook Pro (13-inch, Mid 2012, have been triggered?

- A. Red
- B. Blue
- C. White
- D. Yellow

Answer: A

2.What is the likely cause of an iMac (21.5-inch, Late 2013) producing a single error tone at startup that repeats every five seconds.

- A. The unit does not have RAM or RAM is not installed properly.
- B. The logic board has failed and must be replaced.
- C. The RAM does not pass data integrity tests.
- D. The hard drive has failed S.M.A.R.T. status.

Answer: A

3.Apple recommends a DIMM installation scheme for the Mac Pro (Late 2013) that:

- A. Increases processing power
- B. Enhances graphics processing
- C. Optimizes system cooling
- D. Enables use of special memory modules

Answer: D